Date: March 2, 2012

Kelby Williams, EIT Environmental Corporation of America 1375 Union Hill Industrial Court, Suite A Alpharetta, GA 30004 Office: (770) 667-2040 Tower Engineering Professionals, Inc. 3703 Junction Boulevard Raleigh, NC 27603 (919) 661-6351 <u>Geotech@tepgroup.net</u>

Subject: Subsurface Exploration Report

SBA Designation:	Site Number: Site Name:	CT11934-S Bridgewater 4
Engineering Firm Designation:	TEP Project Number:	120651.10
Site Data:	Wewaka Brook Road, Bridgewater, CT 0675 Latitude N <i>41°30' 31.5''</i> , Longitude W <i>73°21'</i> 170 Foot - Proposed Monopole Tower & Pre	16.0"

Dear Ms. Williams,

Tower Engineering Professionals, Inc. is pleased to submit this **"Subsurface Exploration Report**" to evaluate subsurface conditions in the tower area as they pertain to providing support for the tower foundation.

This report has been prepared in accordance with generally accepted geotechnical engineering practice for specific application to this project. The conclusions in this report are based on the applicable standards of TEP's practice in this geographic area at the time this report was prepared. No other warranty, express or implied, is made.

TEP assumes the current ground surface elevation; tower location and subsequent centerline provided are correct and are consistent with the elevation and centerline to be used for construction of the structure. Should the ground surface elevation be altered and/or the tower location be moved or shifted TEP should be contacted to determine if additional borings are necessary.

The analyses and recommendations submitted herein are based, in part, upon the data obtained from the subsurface exploration. The soil conditions may vary from what is represented in the boring log. While some transitions may be gradual, subsurface conditions in other areas may be quite different. Should actual site conditions vary from those presented in this report, TEP should be provided the opportunity to amend its recommendations as necessary.

We at *Tower Engineering Professionals, Inc.* appreciate the opportunity of providing our continuing professional services to you and Environmental Corporation of America. If you have any questions or need further assistance on this or any other projects please give us a call.

Report Prepared/Reviewed by: Cory A. Bauer / John D. Longest, P.E.

Respectfully submitted by:

Pete Jernigan P.E.





TABLE OF CONTENTS

1) PROJECT DESCRIPTION

2) SITE EXPLORATION

3) SITE CONDITIONS

4) SUBSURFACE CONDITIONS

- 4.1) Soil
- 4.2) Rock
- 4.3) Subsurface Water
- 4.4) Frost

5) TOWER FOUNDATION DESIGN

5.1) Shallow FoundationsTables 1A to 1B - Shallow Foundation Analysis and Rock Parameters5.2) Rock Anchor Foundations

6) TOWER SOIL RESISTIVITY

7) TOWER CONSTRUCTION CONSIDERATIONS - SHALLOW FOUNDATION

7.1) Excavation

- 7.2) Foundation Evaluation/Subgrade Preparation
- 7.3) Rock Anchor Installation
- 7.4) Fill Placement and Compaction
- 7.5) Reuse of Excavated Soil

8) BRIDGE FOUNDATION DESIGN

8.1) Shallow Foundations

Tables 1C to 1G - Shallow Foundation Analysis

9) BRIDGE CONSTRUCTION CONSIDERATIONS - SHALLOW FOUNDATION

- 9.1) Excavation
- 9.2) Foundation Evaluation/Subgrade Preparation
- 9.3) Fill Placement and Compaction
- 9.4) Reuse of Excavated Soil

10) APPENDIX A

Boring Layouts

11) APPENDIX B

Boring Logs

1) PROJECT DESCRIPTION

Based on the preliminary drawings, it is understood a monopole communications tower will be constructed at the referenced site. The structure loads will be provided by the tower manufacturer. In addition the existing access road bridge structure will be replaced by a precast concrete bridge. The structure loads will be provided by the bridge manufacturer.

2) SITE EXPLORATION

The field exploration included the performance of six soil test borings (B-1, B-2, B-3, B-4, B-5 and B-6) to the planned depth of 35 to 36.5 feet (bgs) at the approximate centerline of the proposed bridge corners, to the planned depth 36 feet (bgs) at the approximate centerline of the access road west of the proposed bridge and to the auger refusal depth of 8 feet (bgs) at the approximate centerline of the proposed monopole tower. The borings were performed by an ATV mounted drill rig using continuous flight hollow stem augers to advance the hole. Split-spoon samples and Standard Penetration Resistance Values (N-values) were obtained in accordance with ASTM D 1586 at a frequency of 1 sample every 5 feet to the termination of the bridge and road borings and 2 samples to auger refusal in the tower boring.

The Split-spoon samples were transported to the TEP laboratory where they were classified by a Geotechnical Engineer in general accordance with the Unified Soil Classification System (USCS), using visual-manual identification procedures (ASTM D 2488).

Diamond-bit core drilling procedures were used to help determine the character and continuity of the rock in boring B-6. The core drilling procedures were in accordance with ASTM Specification D-2113. Rock core samples of the materials penetrated were protected and retained in a swivel-mounted inner tube of the core barrel. Upon completion of the drill run, the core barrel was brought to the surface and samples removed and placed in standard boxes. The samples were classified by a Geotechnical Engineer and the "Recovery" and "Rock Quality Designation" were determined.

The "Recovery" is the ratio of the sample length obtained to the length drilled, expressed as a percent. The "Rock Quality Designation" (RQD) is the percent of the recovered rock samples in lengths of four or more inches, compared to the total length of the core run. This designation is generally applied to samples of NWX size (2-1/8 inch diameter) or larger and to samples described as moderately hard or harder. The percent recovery and RQD are related to rock soundness and continuity. Generalized rock descriptions, percent recovery, and the RQD value are shown on the boring log.

A Boring Location Plan showing the approximate boring locations, the Boring Logs presenting the subsurface information obtained and a brief guide to interpreting the boring logs are included in the Appendix.

3) SITE CONDITIONS

The site is located off Wewaka Brook Road in Bridgewater, Litchfield County, Connecticut. The proposed tower and compound are to be located in a wooded area on a ridge. The ground topography is sloping. The proposed precast concrete bridge is to be located in a clearing along the access road. The ground topography is relatively flat to slightly sloping.





4) SUBSURFACE CONDITIONS

The following description of subsurface conditions is brief and general. For more detailed information, the individual Boring Logs contained in Appendix B - Boring Logs may be consulted.

4.1) Soil

The USCS classification of the materials encountered in the boring include SP-SM, SP, SW-SM, SM and Gneiss. The Standard Penetration Resistance ("N" Values) recorded in the materials ranged from 5 blows per foot to 100 blows per 1 inch of penetration.

4.2) Rock

Gneiss was encountered at a depth of 8 feet (bgs) in boring B-1. Refusal of auger advancement was encountered at a depth of 8 feet (bgs) in boring B-1.

4.3) Subsurface Water

Subsurface water was encountered at a depth of 4 to 9 feet (bgs) in borings B-1, B-3 and B-6 at the time of drilling. It should be noted the subsurface water level will fluctuate during the year, due to seasonal variations and construction activity in the area.

4.4) Frost

The TIA frost depth for Litchfield County Connecticut is 40 inches.

5) TOWER FOUNDATION DESIGN

Based on the boring data, it is the opinion of TEP that a pier extending to a single large mat foundation can used to support the new tower. The following presents TEP's conclusions and recommendations regarding the foundation type.

5.1) Shallow Foundation

The foundation should bear a minimum of 3.5 feet below the ground surface to penetrate the frost depth and with sufficient depth to withstand the overturning of the tower. To resist the overturning moment, the weight of the concrete and any soil directly above the foundation can be used. A friction factor of 0.50 can be utilized at this depth. The values are based on the current ground surface elevation.

De	pth	Soil	Static Bearing ¹	Cohesion ^{2,3}	Friction Angle ²	Effective Unit	
Тор	Bottom	3011	(psf)	(psf)	(degrees)	Weight (pcf)	
0	4	SM	1975	-	31	117	
4	8	SM	11175	-	45	122	
8	13	Gneiss ³	67,300 ⁴	-	45	145	

Table 1A – Shallow Foundation Analysis Parameters – Boring B-6

Notes:

1) The bearing values provided are net allowable with a minimum factor of safety of 2 with anticipated settlement less than 1 inch. Bearing may be increased by 1/3 for transient loading (e.g. wind or earthquake loading)

2) These values should be considered ultimate soil parameters

3) In cases where the shear failure is likely to develop along planes of discontinuity or through highly fractured rock masses cohesion cannot be relied upon to provide resistance to failure

4) Due to the fractured nature of the rock sample. Cohesion of the rock cannot be relied upon for strength parameters. Indicated layers have been evaluated as a granular material

Dej	pth	Bock			Unconfined Compressive	Grout/Rock ^{1,2} Bond Stress	Effective Unit
Тор	Bottom				Strength (psi)	(psi)	Weight (pcf)
8	13	Gneiss	100	70	8830	875	145

Table 1B – Rock Parameters – Boring B-6

Notes: 1)

These values should be considered ultimate rock parameters. A minimum factor of safety of 4 should be utilized

2) The rock encountered is not considered competent, see section 5.2 for design recommendations

5.2) Rock Anchor Foundations

Rock anchor design considerations are being provided should they become necessary for foundation installation. The rock anchors should consist of high strength grouted rock bolts (tensioned anchors). The anchors should extend into the competent rock and have the embedment necessary to resist the applied loads. Group effects can cause significant reductions in calculated resistance. Considerations for group effects should be given for rock anchor designs that utilize multiple closely spaced anchors. Competent rock was not encountered at the time of the exploration. Rock competency is typically estimated based on compressive strength of the intact rock, RQD value, joint spacing, condition of the joints, and ground water conditions.

Embedment depths for cement grout bonded rock anchors are often determined by using the rock cone method. Unlike a mechanical anchor, a bonded anchor must include a bond length in the embedment depth. The bond length allows the applied tensile load to be transferred to the surrounding rock. Therefore the embedment depth of a pre-stressed bonded rock anchor is made up of the free-stress length and the bond length.

Bond resistance values are typically estimated from the unconfined compressive strength of the rock. However, design values obtained from laboratory tests on small specimens should be adjusted to account for scale effects. For bond resistance values, TEP recommends an ultimate value of 875 psi be used for design. TEP recommends that a factor of safety of 4 be utilized given the limited extent of the boring. The bond resistance value should be applied to rock that is considered competent. Rock samples with near 100% recovery, RQD values greater than 75%, slightly rough to very rough rock surfaces and joint gaps less than 1 mm can be considered competent. TEP recommends that 50% of all rock anchor or a minimum of 4 be proof loaded to 80% of their design load to verify their adequacy.

6) TOWER SOIL RESISTIVITY

Soil resistivity was performed at the TEP laboratory in accordance with ASTM G187-05 (Standard Test Method for Measurement of Soil Resistivity Using the Two Electrode Soil Box Method). Test results indicated a result of 145,000 ohms/cm.

7) TOWER CONSTRUCTION CONSIDERATIONS - SHALLOW FOUNDATION

7.1) Excavation

The boring data indicates excavation to the expected subgrade level for the shallow foundation will extend through sand and rock. A large tracked excavator should be able to remove the soil materials with minimal difficulty. A large tracked excavator with rock teeth and/or a pneumatic hammer will be necessary to remove the rock materials with difficulty. TEP anticipates the depth to the surface of the rock will vary outside of the boring location.

Excavations should be sloped or shored in accordance with local, state and federal regulations, including OSHA (29 CFR Part 1926) excavation trench safety standards. It is the responsibility of the contractor for site safety. This information is provided as a service and under no circumstance should TEP be assumed responsible for construction site safety.

7.2) Dewatering/Foundation Evaluation/Subgrade Preparation

As previously discussed, subsurface water was encountered in the boring at a depth of 4 feet (bgs). Therefore, dewatering (using pumped sumps or well points) may be required for construction purposes at this site. The subsurface water level should be kept below the bottom level of any excavation. After dewatering and excavation to the design elevation for the footing, the materials should be evaluated by a Geotechnical Engineer or a representative of the Geotechnical Engineer prior to reinforcement and concrete placement. This evaluation should include probing, shallow hand auger borings and dynamic cone penetrometer testing (ASTM STP-399) to help verify that suitable residual material lies directly under the foundation and to determine the need for any undercut and replacement of unsuitable materials. Loose surficial material should be compacted in the excavation prior to reinforcement and concrete placement to stabilize surface soil that may have become loose during the excavation process. TEP recommends a 6-inch layer of compacted crushed stone be placed just after excavation to aid in surface stability.

7.3) Rock Anchor Installation

Rock anchor materials verification and installation should be evaluated by a Geotechnical Engineer or a representative of the Geotechnical Engineer during installation to verify compliance with materials manufacturer and foundation design specifications.

7.4) Fill Placement and Compaction

Backfill materials placed above the shallow foundation to the design subgrade elevation should not contain more than 5 percent by weight of organic matter, waste, debris or any otherwise deleterious materials. To be considered for use, backfill materials should have a maximum dry density of at least 100 pounds per cubic foot as determined by standard Proctor (ASTM D 698), a Liquid Limit no greater than 40, a Plasticity Index no greater than 20, a maximum particle size of 4 inches, and 20 percent or less of the material having a particle size between 2 and 4 inches. Because small handheld or walkbehind compaction equipment will most likely be used, backfill should be placed in thin horizontal lifts not exceeding 6 inches (loose).

Fill placement should be monitored by a qualified Materials Technician working under the direction of a Geotechnical Engineer. In addition to the visual evaluation, a sufficient amount of in-place field density tests should be conducted to confirm the required compaction is being attained.

7.5) Reuse of Excavated Soil

The sand that meets the above referenced criteria can be utilized as backfill based on dry soil and site conditions at the time of construction.

dense.	-
4	



8) BRIDGE FOUNDATION DESIGN

Based on the information provided to TEP, the existing bridge structure will be replaced by a precast concrete bridge. TEP was not provided with bridge drawings or plans. TEP assumes the bridge will be supported on shallow foundations. TEP would like the opportunity to review the precast bridge plans when available to provide any revisions to the geotechnical report.

8.1) Shallow Foundation

The foundations should bear a minimum of 3.5 feet below the ground surface to penetrate the frost depth.

De	pth	Soil	Static Bearing ¹	Cohesion ²	Friction Angle ²	Effective Unit
Тор	Bottom	301	(psf)	(psf)	(degrees)	Weight (pcf)
0	5	SP-SM	1850	-	32	117
5	9	SW-SM/Boulder ⁴	8875 ⁵	-	41	120
9	15	SP	20200	-	45	60
15	20	SP	23625	-	45	60
20	25	SP	25800	-	45	60
25	30	SP-SM	27225	-	45	60

Table 1C – Shallow Foundation Analysis Parameters – Boring B-1

Table 1D – Shallow Foundation Analysis Parameters – Boring B-2

De	pth	Soil	Static Bearing ¹	Cohesion ²	Friction Angle ²	Effective Unit	
Тор	Bottom	501	(psf)	(psf)	(degrees)	Weight ³ (pcf)	
0	5	SW-SM	7300	-	45	122	
5	9.5	SW-SM	8825	-	40	120	
9.5	15	SP-SM	9050	-	40	58	
15	20	SP-SM	21350	-	45	60	
20	25	SP-SM	33375	-	45	60	
25	30	SP-SM	33075	-	45	60	

Table 1E – Shallow Foundation Analysis Parameters – Boring B-3

De	pth	Soil	Static Bearing ¹	Cohesion ²	Friction Angle ²	Effective Unit	
Тор	Bottom	301	(psf)	(psf)	(degrees)	Weight (pcf)	
0	5	SM	1850	-	32	117	
5	7.4	SW-SM/Boulder ⁴	8375 ⁵	-	41	120	
7.4	15	SP-SM	8925	-	41	58	
15	20	SP-SM	11125	-	42	58	
20	25	SP-SM	12150	-	45	60	
25	30	SW-SM	12825	-	45	60	



De	pth	Soil	Static Bearing ¹	Cohesion ²	Friction Angle ²	Effective Unit
Тор	Bottom	5011	(psf) (psf)		(degrees)	Weight ³ (pcf)
0	5	SM	1575	-	31	117
5	10	SM	5800	-	34	55
10	15	SP-SM	17325	-	45	60
15	20	SP-SM	22625	-	45	60
20	25	SP-SM	24700	-	45	60
25	30	SP-SM	26075	-	45	60

Table 1F – Shallow Foundation Analysis Parameters – Boring B-4

Table 1G – Shallow Foundation Analysis Parameters – Boring B-5

De	Depth		Static Bearing ¹	Cohesion ²	Friction Angle ²	Effective Unit	
Тор	Bottom	Soil	(psf) (psf)		(degrees)	Weight ³ (pcf)	
0	5	SP-SM	1625	-	32	117	
5	10	SP-SM	10275	-	45	56	
10	15	SP-SM	15100	-	45	60	
15	20	SP-SM	17125	-	45	60	
20	25	SP-SM	18725	-	45	60	
25	30	SP-SM	19750	-	45	60	

Notes:

1. The bearing values provided are net allowable with a minimum factor of safety of 2 with anticipated settlement less than 1 inch. Bearing may be increased by 1/3 for transient loading (e.g. wind or earthquake loading)

2. These values should be considered ultimate soil parameters

Subsurface water level is based on an average groundwater elevation in nearby borings Classifications are based on soil layers in additional borings in relatively close proximity 3.

4.

5. In order to bear on this layer, soils should be verified

6. $K_0 = 1 \text{-sin}\phi$

7. $K_a = tan^2(45-\phi) = 1/K_p$

9) BRIDGE CONSTRUCTION CONSIDERATIONS - SHALLOW FOUNDATION

9.1) Excavation

The boring data indicates excavation to the expected subgrade level for the bridge foundations will extend through sand. A large tracked excavator should be able to remove the soil materials with minimal difficulty. Boulders and bedrock outcroppings are common to this geographic region and may be encountered outside of the boring locations.

Excavations should be sloped or shored in accordance with local, state and federal regulations, including OSHA (29 CFR Part 1926) excavation trench safety standards. It is the responsibility of the contractor for site safety. This information is provided as a service and under no circumstance should TEP be assumed responsible for construction site safety.

9.2) Dewatering/Foundation Evaluation/Subgrade Preparation

As previously discussed, subsurface water was encountered in borings B-1 and B-3 at a depth of 7.4 to 9 feet (bgs) and anticipated to be at 5 feet (bgs) in borings B-4 and B-5. Therefore, dewatering (using pumped sumps or well points) may be required for construction purposes at this site. The subsurface water level should be kept below the bottom level of any excavation. After dewatering and excavation to the design elevation for the footing, the materials should be evaluated by a Geotechnical Engineer or a representative of the Geotechnical Engineer prior to reinforcement and concrete placement. This evaluation should include probing, shallow hand auger borings and dynamic cone penetrometer testing (ASTM STP-399) to help verify that suitable residual material lies directly under the foundation and to determine the need for any undercut and replacement of unsuitable materials. Loose surficial material should be compacted in the excavation prior to reinforcement and concrete placement to stabilize surface soil that may have become loose during the excavation process. TEP recommends a 6-inch layer of compacted crushed stone be placed just after excavation to aid in surface stability. TEP recommends a proper drainage system be installed to divert water away from underneath and behind abutments and foundations.

9.3) Fill Placement and Compaction

Backfill materials placed above the shallow foundation to the design subgrade elevation should not contain more than 5 percent by weight of organic matter, waste, debris or any otherwise deleterious materials. To be considered for use, backfill materials should have a maximum dry density of at least 100 pounds per cubic foot as determined by standard Proctor (ASTM D 698), a Liquid Limit no greater than 40, a Plasticity Index no greater than 20, a maximum particle size of 4 inches, and 20 percent or less of the material having a particle size between 2 and 4 inches and have a friction angle of at least 30 degrees. Because small handheld or walk-behind compaction equipment will most likely be used, backfill should be placed in thin horizontal lifts not exceeding 6 inches (loose).

Fill placement should be monitored by a qualified Materials Technician working under the direction of a Geotechnical Engineer. In addition to the visual evaluation, a sufficient amount of in-place field density tests should be conducted to confirm the required compaction is being attained.

9.4) Reuse of Excavated Soil

The sand that meets the above referenced criteria can be utilized as backfill based on dry soil and site conditions at the time of construction.

If variability in the subsurface materials is encountered, a representative of the Geotechnical Engineer should verify that the design parameters are valid during construction. Modification to the design values presented above may be required in the field.







APPENDIX A

BORING LAYOUTS








APPENDIX B

BORING LOGS



Key to Log of Boring

Sheet 1 of 1



- 1. Soil classifications are based on the Unified Soil Classification System. Descriptions and stratum lines are interpretive, and actual lithologic changes may be gradual. Field descriptions may have been modified to reflect results of lab tests.
- 2. Descriptions on these logs apply only at the specific boring locations and at the time the borings were advanced. They are not warranted to be representative of subsurface conditions at other locations or times.

Figure 1 thru 6

Log of Boring B-1

Date(s) Drilled February 21, 2012	Logged By Cory Bauer	Checked By John Longest		
Drilling Method Hollow Stem Auger	Drill Bit Size/Type	Total Depth of Borehole 35 feet bgs		
Drill Rig Type ATV	Drilling Contractor TEP	Approximate Surface Elevation 489 feet AMSL		
Groundwater Level and Date Measured 9 feet ATD		Hammer Data 140 lb, 30 in drop, Auto Hammer		
Borehole Backfill Cuttings	Location Approximate centerline of the pro	Location Approximate centerline of the proposed northwest bridge support		

Elevation, feet	Depth, feet	Sample Type	Sample Number	Sampling Resistance, blows/foot	Relative Consistency	USCS Symbol	Graphic Log	MATERIAL DESCRIPTION	REMARKS AND OTHER TESTS
489	0 -		S1	7	Loose	SP- SM		Dark brown, fine to medium, poorly graded SAND (SP-SM), with silt, moist	-
- 484 - -	- - 5 -		S2	50/0"				- No Recovery	Driller Note: Bouncing on Boulder
- 479	- - 10—				Very	SP		- (ATD) \[-
_	-		S3	88/8"	Dense	0.			-
- 474 - -	- 15— -		S4	68		SP		- 	-
- 469 - -	- 20 - -		S5	97/11"					-
- 464— - -	- 25— -		S6	147/11"	Very Dense	SP- SM		Gray, fine to medium, poorly graded SAND (SP-SM), with silt, moist	-
- 459 - -	- 30— -		S7	159					-
- 454 - -	- 35 - -	-						Bottom of Boring at 35 feet bgs	Driller Note: Attempted to sample, sppon broke in hole
49	40—								Figure 1

Log of Boring B-2

Date(s) Drilled February 21, 2012	Logged By Cory Bauer	Checked By John Longest	
Drilling Method Hollow Stem Auger	Drill Bit Size/Type	Total Depth of Borehole 36 feet bgs	
Drill Rig Type ATV	Drilling Contractor TEP	Approximate Surface Elevation 491 feet AMSL	
Groundwater Level and Date Measured Not Encountered ATD	Sampling Method(s) SPT	Hammer Data 140 Ib, 30 in drop, Auto Hammer	
Borehole Backfill Cuttings	Location Approximate centerline of the proposed access road west of the proposed bridge		

Elevation, feet		Sample Type	Sample Number	Sampling Resistance, blows/foot	Relative Consistency	USCS Symbol	Graphic Log	MATERIAL DESCRIPTION	REMARKS AND OTHER TESTS
491— – –	-0 - -		S1	55	Very Dense	SW- SM		Brown, fine to medium, well graded SAND (SW-SM), with silt, with gravel, moist	-
- 486 -	- 5 -		S2	21	Medium Dense	SW- SM		 ↓ to medium dense, wet	-
- 481— -	- - 10 -		S3	23	Medium Dense	SP- SM		Brown and gray, fine to medium, poorly graded SAND (SP-SM), with silt, with mica, moist	
- 476— -	- 15 -		S4	60	Very Dense	SP- SM		V to very dense, gray	
- 471— -	- 20 - -		S5	113					-
- 466— - -	- 25 - -		S6	159/9"					-
_ 461— _ _	- 30— -		S7	100/5"				- · · · · · · · · · · · · · · · · · · ·	-
- 456— -	- 35 -		S9	100/6"				Bottom of Boring at 36 feet bgs	
- - 451	- - 40								Figure 2

Log of Boring B-3

Date(s) Drilled February 20, 2012	Logged By Cory Bauer	Checked By John Longest
Drilling Method Hollow Stem Auger	Drill Bit Size/Type	Total Depth of Borehole 35.5 feet bgs
Drill Rig Type ATV	Drilling Contractor TEP	Approximate Surface Elevation 489 feet AMSL
Groundwater Level and Date Measured 7.4 feet ATD	Sampling Method(s) SPT	Hammer Data 140 lb, 30 in drop, Auto Hammer
Borehole Backfill Cuttings	Location Approximate centerline of the pro	pposed southwest bridge support

Elevation, feet	Depth, feet	Sample Type	Sample Number	Sampling Resistance, blows/foot	Relative Consistency	USCS Symbol	Graphic Log	MATERIAL DESCRIPTION	REMARKS AND OTHER TESTS
489	0 -		S1	6	Loose	SM		Dark brown, fine silty SAND (SM), trace roots, trace gravel, moist	-
- - 484 - -	- - 5 -		S2	50/2*				 	Driller Note: Bouncing on boulder
- - 479 - -	- - 10 - -		S3	23	Medium Dense	SP- SM		Light brown, fine to medium, poorly graded SAND (SP-SM), with silt, wet	-
- 474 - -	- 15— - -		S4	24		SP- SM		√ trace gravel	-
_ 469— _ _ _	- 20— - -		S5	70	Very Dense	SP- SM		↓ to very dense, with mica, no gravel, moist, gray	-
- 464 - -	- 25— - -		S6	100/6"	Very Dense	SW- SM		Gray, fine to medium, well graded SAND (SW-SM), with fine to coarse gravel, with silt, with mica, moist	-
- 459 - -	- 30— - -		S7	100/5"	Very Dense	SP- SM		Gray, fine to medium, poorly graded SAND (SP-SM), with silt, with mica, moist	-
_ 454 _ _ _	- 35— - -	33	S9	100/5"					
149	- 40—								Figure 3


Log of Boring B-4

Date(s) Drilled February 20, 2012	Logged By Cory Bauer	Checked By John Longest
Drilling Method Hollow Stem Auger	Drill Bit Size/Type	Total Depth of Borehole 36.5 feet bgs
Drill Rig Type ATV	Drilling Contractor TEP	Approximate Surface Elevation 486 feet AMSL
Groundwater Level and Date Measured Not Encountered ATD	Sampling Method(s) SPT	Hammer Data 140 lb, 30 in drop, Auto Hammer
Borehole Backfill Cuttings	Location Approximate centerline of the pro	posed northeast bridge support

Elevation, feet	Depth, feet	Sample Type	Sample Number	Sampling Resistance, blows/foot	Relative Consistency	USCS Symbol	Graphic Log	MATERIAL DESCRIPTION	REMARKS AND OTHER TESTS
486	0		S1	5	Loose	SM		Dark brown, fine silty SAND (SM), trace roots, moist	-
- 481 - -	- 5— -		S2	10		SM		- 	-
- 476 - -	- - 10 -		S3	48	Dense	SP- SM		Gray, fine to medium, poorly graded SAND (SP-SM), with silt, with mica, moist	- - - -
- 471 - -	- - 15 - -		S4	63	Very Dense	SP- SM		- - - ↓ to very dense 	- - - -
_ 466— _ _ _	- 20— -		S5	64				- 	-
- 461— - -	- 25— - -		S6	72					-
_ 456— _ _ _	- 30— - -		S7	105				- 	-
451— - -	- 35— - -		S9	156				- 	
446	- 40—							-	- Figure 4

Log of Boring B-5

Date(s) Drilled February 20, 2012	Logged By Cory Bauer	Checked By John Longest
Drilling Method Hollow Stem Auger	Drill Bit Size/Type	Total Depth of Borehole 36.5 feet bgs
Drill Rig Type ATV	Drilling Contractor TEP	Approximate Surface Elevation 486 feet AMSL
Groundwater Level and Date Measured Not Encountered ATD	Sampling Method(s) SPT	Hammer Data 140 lb, 30 in drop, Auto Hammer
Borehole Backfill Cuttings	Location Approximate centerline of the pro	posed southeast bridge support



Log of Boring B-6

Date(s) Drilled February 20, 2012	Logged By Cory Bauer	Checked By John Longest
Drilling Method Hollow Stem Auger	Drill Bit Size/Type	Total Depth of Borehole 13 feet bgs
Drill Rig Type ATV	Drilling Contractor TEP	Approximate Surface Elevation 583 feet AMSL
Groundwater Level and Date Measured 4 feet ATD	Sampling Method(s) SPT, Other	Hammer Data 140 Ib, 30 in drop, Auto Hammer
Borehole Backfill Cuttings	Location Approximate centerline of the prop	posed monopole tower

Elevation, feet	Depth, feet	Sample Type	Sample Number	Sampling Resistance, blows/foot	Relative Consistency	USCS Symbol	Graphic Log	MATERIAL DESCRIPTION	REMARKS AND OTHER TESTS
583	-0		S1	5	Loose	SM		Brown, fine silty SAND (SM), trace gravel, trace roots, moist	-
- 578— -	- 5—		S2	100/1"				- (ATD) \= No Recovery	Driller Note: Steady grinding
- - 573—	- - - 10—	-				GNEISS		Auger Refusal at 8 feet bgs-Rock Core-Gray, moderately fractured GNEISS (Recovery 100%, Rock Quality Designation 70%, Unconfined Compressive Strength 8830 psi)	Rec=100%, RQD=70%
-	-		R1					Bottom of Boring at 13 feet bgs	
568	- 15—								Figure 6